## **COMPUTER PREVENTIVE MAINTENANCE CHECKLIST**

	User Signature		·	<del>_</del>	Date:_	2023-07-17
(	Conducted by:	Payer U		Ducert		
Department: Factore T-ASSY / Production						
PC no. : 1FXC 046 0						
Factory no.: Factory 2						
	TT Class	Buet on C	:DII			}
Clean Dust on CPU						
☑ Deleting Temp/Junk Files ☑ Antivirus Scan						
☐ Antivirus Scari ☐ Disabling Hotspot						
☐ Disabiling Hotspot ☐ Windows Update( Optional )						
☑ Remove/Uninstall Unwanted Program						
	Check M	lonitor/Scr	een for l	Defect		
☑ OK □Not OK						
Check Charger for Defect						
ÓOK □Not OK						
Check Keyboard Casing						
図OK □Not OK						
Check Lan Connection						
MA OK ONOTOK WIFT CONTY						
Check battery life						
		⊴ OK	□Not	OK		
	Others:					7
		<u> </u>				
Reminders:						
Must bring this following tools to perform the Computer Preventive						
Maintenance ( CPM ), the tools are screwdriver, brush, blower, eraser,						
crimper and RJ45.						
	<del></del>			·	Related Documents:	TCF-G116
Document No:	TCF-G112	VER.	2	Toyofley Cel	bu Corporation	RETENTION PERIOD
Document No:	101-0112	Prepared by:		Checked by:	Approved by:	

10 YEARS

Amadito Ortizano

Rey Dagatan

Efectivity Date:

2023-07-15

Rushky Estrera