COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature:_	
Conducted by:	ORVEINE PAUL ALMAGRO
Department:	ine conf
PC no.: TEX CIO	•

Date: 2023-07-19

	- .				
7	Clean	Dust	on	CPU	ŀ

- ☑ Deleting Temp/Junk Files
- ☑ Antivirus Scan

Factory no. : FACTORY 6

- ☑ Disabling Hotspot
- ☑ Windows Update(Optional)
- ☑ Remove/Uninstall Unwanted Program

Check Monitor/Screen for Defect

☑ OK □Not OK

Check Charger for Defect

☑ OK □Not OK

Check Keyboard Casing

☑ OK □Not OK

Check Lan Connection

☑ OK □Not OK

Check battery life

☑ OK □Not OK

Others:

PASL 3

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents:					TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation	RETENTION PERIOD
Efectivity Date:	2023-07-15	Prepared by:		Checked by: Approved by:	10 YEARS
Electivity Date.	2023-07-13	Rushky E	Estrera	Rey Dagatan Amadito Ortizano	