COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature:	Date: 2023-07-19						
Conducted by: Podel James Durente							
Department: RRING COIL / Klork							
PC no. : TEXC0261							
Factory no.: Factory 6							
•							
☐ Clean Dust on CPU							
☐ Deleting Temp/Junk Files							
☑ Antivirus Scan							
☑ Disabling Hotspot							
☑ Windows Update(Optional)							
☑ Remove/Uninstall Unwanted Program							
· .							
Check Monitor/Screen for Defect							
☐ OK ☐ Not OK							
Check Charger for Defect							
n/A □ OK □Not OK							
Check Keyboard Casing ☑ OK □Not OK							
Check Lan Connection							
☐ OK ☐ Not OK							
Check battery life							
MA □ OK □Not OK							
`							
Others:							
Kiosk Marchine							

Reminders:

must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

. PS

			Related Documents: TFJ-S16-G008			
Document No:	TCF-G112	VER.	2	Toyoflex C	ebu Corporation	RETENTION PERIOD
		Prepared by: Rushky Estrera		Checked by:	Approved by:	
Efectivity Date:	2023-07-15			Rey Dagatan	Amadito Ortizano	10 YEARS