GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.0
User Signatur	1	29 -07-10
Conducted by		
Department:_		
PC no. :	XC 00 30 Jp. TFXC 0876	
Factory no. :_	MEDICAL FACTORY	
□ Clear	n Dust on CPU	
□ Delef	ing Temp/Junk Files	
	irus Scan	
□ Disate	oling Hotspot	
☐ Wind	ows Update( Optional )	
□ Rem	ove/Uninstall Unwanted Program	
Check I	Monitor/Screen for Defect	
011	☑ OK □Not OK	
Check	Charger for Defect	
Check I	☑ OK □Not OK Keyboard Casing	
Ondoki	☑ OK □Not OK	
Check I	an Connection	
	☑ OK □Not OK	
Check b	pattery life	
	☑ OK □Not OK	
Others:		

Must bring this following tools to perform the Computer Preventive Maintenance ( CPM ), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

<sup>\*</sup>It is permitted to use this form in both electronic and hard copy.

<sup>\*</sup>The user have to check and compare versions, effective date and sub master information before printing.