GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
User Signature: Conducted by: Marte Sarres Department: STRL PC no.: TRX 6 0 7 1 7 Factory no.: Mrd((2))		
☑ Delet ☑ Antivi ☑ Disab □ Wind	n Dust on CPU ing Temp/Junk Files irus Scan oling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program	·
Check to Check L	Monitor/Screen for Defect ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Keyboard Casing ☐ OK ☐ Not OK Lan Connection ☐ OK ☐ Not OK Dattery life ☐ OK ☐ Not OK	
Others:		
_	s following tools to perform the Computer Preventive (CPM), the tools are screwdriver, brush, blower, eraser, RJ45.	Related Documents: TMF-G0058

!

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.