COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature: Note 2013- 08-21 Conducted by: KNAVEN JADE PARAN	Date: 2024	-08-21
Conducted by		
Department: WR Warehouse		
PC no.: 7 to 60 logs		
Factory no.: Factory 3		
☐ Clean Dust on CPU		
☑ Deleting Temp/Junk Files		
☑ Antivirus Scan		
☐ Disabling Hotspot		
☑ Windows Update(Optional)		
☑ Remove/Uninstall Unwanted Program		
Check Monitor/Screen for Defect		
□ OK □Not OK		
Check Charger for Defect		
Charle Kontrol Coning		
Check Keyboard Casing		
☐ OK ☐ Not OK Check Lan Connection		
□ OK □Not OK		
Check battery life		
Øriccik battery inte		
E OR LINGUOR		
Othora		
Others:		
Reminders:		
Must bring this following tools to perform the Comp	uter Preventive	
Maintenance (CPM), the tools are screwdriver, bro		
crimper and RJ45.	•	
	Related Documents:	TCF-G116
r	reiated Documents.	101-0110

2

Rushky Estrera

Checked by:

Rey Dagatan

VER.
Prepared by:

Document No:

Efectivity Date:

TCF-G112

2023-07-15

Toyoflex Cebu Corporation

Approved by:

Amadito Ortizano

RETENTION PERIOD

10 YEARS