COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature: GUSETTE TIME Date: 2013 - 001-05

Conducted by:

Department: GA-IT

PC no.: FACTORY 1

- ☑ Clean Dust on CPU
- ☑ Deleting Temp/Junk Files
- ☑ Antivirus Scan
- Disabling Hotspot
- ☑ Windows Update(Optional)
- ☑ Remove/Uninstall Unwanted Program

Check Monitor/Screen for Defect

☑ OK □Not OK

Check Charger for Defect

☑ OK □Not OK

Check Keyboard Casing

☑ OK ☐ Not OK

Check Lan Connection

☑ OK □Not OK

Check battery life

☑ OK □ Not OK

Others:

FIREWALL : LEVEL 3

Reminders:

must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

| | | | | | Related Documents: | TFJ-S16-G008 |
|------------------|------------|------------------------------|---|---------------------------|--------------------|------------------|
| Document No: | TCF-G112 | VER. | 2 | Toyoflex Cebu Corporation | | RETENTION PERIOD |
| | | Prepared by: Rushky Estrera | | Checked by: | Approved by: | |
| Efectivity Date: | 2023-07-15 | | | Rey Dagatan | Amadito Ortizano | 10 YEARS |