COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

	_	<u>-</u>		
User Signature	e:/	/ -		
Conducted by: <u>susette surbano</u>				
Department:	T-AGGY	07-QC		
PC no. :	TFX C0670			
Factory no. :	FACTOR	20 2		

Date: 20	29-	07-	П
----------	-----	-----	---

- ☐ Clean Dust on CPU
- ☑ Deleting Temp/Junk Files
- ☑ Antivirus Scan
- ☑ Disabling Hotspot
- ☑ Windows Update(Optional)
- ☑ Remove/Uninstall Unwanted Program

Check Monitor/Screen for Defect

☑ OK □Not OK

Check Charger for Defect

✓ OK □Not OK

Check Keyboard Casing

☑ OK □Not OK

Check Lan Connection

☑ OK ☐ Not OK

Check battery life

☑ OK □Not OK

Others:

LYWING LAN CONNECTION

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

					Related Documents:	TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Ce	ebu Corporation	RETENTION PERIOD
Efectivity Date: 2023-07-15		Prepared by:		Checked by:	Approved by:	40 VE ADS
		Rushky	Estrera	Rey Dagatar	n Amadito Ortízano	10 YEARS