User Signature: M: Mario Carrosa  Conducted by: Mario Carrosa  Department: Accounting PC no.: Trxc0400  Factory no.: MpMi(3)  Clean Dust on CPU  Deleting Temp/Junk Files  Antivirus Scan  Disabling Hotspot	KLIST  Date: 20	Version 1.00
Conducted by: Mario (arrosa  Department: Accounting  PC no.: Tfxc 04 00  Factory no.: Mpdi(3)  ☐ Clean Dust on CPU ☐ Deleting Temp/Junk Files ☐ Antivirus Scan	Date: 20	23-08-09
<ul><li>☑ Deleting Temp/Junk Files</li><li>☑ Antivirus Scan</li></ul>		
<ul> <li>□ Windows Update( Optional )</li> <li>□ Remove/Uninstall Unwanted Program</li> </ul>		
Check Monitor/Screen for Defect  ☐ OK ☐ Not OK  Check Charger for Defect ☐ OK ☐ Not OK  Check Keyboard Casing ☐ OK ☐ Not OK  Check Lan Connection ☐ OK ☐ Not OK  Check battery life ☐ OK ☐ Not OK		
Others:		

Must bring this following tools to perform the Computer Preventive Maintenance ( CPM ), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

<sup>\*</sup>It is permitted to use this form in both electronic and hard copy.

<sup>\*</sup>The user have to check and compare versions, effective date and sub master information before printing.