GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
User Signatu	2023-08-08	
	y: Marlo (arrosa	.023 - 08 - 07
	ΦΕ	
	0 5 9 4	
	Midical	
	W.C.	
	an Dust on CPU	
	eting Temp/Junk Files	
	virus Scan	
	abling Hotspot	
□ Win	dows Update(Optional)	
□ Rem	nove/Uninstall Unwanted Program	
Check	Monitor/Screen for Defect	
OTIOOK	☑ OK □Not OK	
Check	Charger for Defect	
	☑ OK □Not OK	
Check	Keyboard Casing	
	□ OK □ Not OK	
Check	Lan Connection	
	☑ OK □Not OK	
Check	battery life	
	☑ OK □Not OK	
Others	5:	

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.