	arduino	sending messages over serial
	Ground	first bit is command
2	10	1 - set colour 1
2	11	2 - set colour 2 3 - transition colour 1
		4 - transition colour 2
2	9	5 - transitions both
		6 - sets transition speeds
		normal squence of commands would be
1	3	01FFFFFF <in all="" hex="" set="" white<br="">03 <transition colours<="" th=""></transition></in>
1	6	
1	5	