

Overview: Part of spill impact on 10" Ekulama2 delivery line at Ekulama. Picture taken during Joint Investigation of 12th June, 2011



<u>Close-up:</u> Spill due to tear on 10" Ekulama2 delivery line at Ekulama. Picture taken during
Joint Investigation of 12<sup>th</sup> June, 2011

1