

Overview: Part of spill impact on Awoba Well8T flowline at Bille. Picture was taken during Joint Investigation of 6th December, 2011.



<u>Close-up:</u> Approximate location of pinhole due to corrosion on Awoba Well8T flowline riser at Bille. Picture was taken during Joint Investigation of 6th December, 2011.