

Overview: Extent of spill incident impact on the 10in Utorogu-UPS trunkline at lwhrekan. Picture was taken during JIV of 7th June 2011.



 $\underline{\text{Close-up:}} \ \text{Repair clamps on the 10in Utorogu-UPS trunkline at lwhrekan. Picture was taken during JIV of $7^{th}$ June 2011.}$ 

1