

Overview: Part of spill impact on 16" Uzere-Eriemu trunkline right of way at lyede. Picture was taken during Joint Investigation of $5^{\rm th}$ July 2012.



<u>Close up:</u> Illegal fitting on 16" Uzere-Eriemu trunkline at Iyede. Picture was taken during Joint Investigation of $5^{\rm th}$ July 2012.

1