

Overview: Part of spill impact on 12" ImoRiver2 pipeline at Odagwa. Picture taken during Joint Investigation of 17th June, 2011



<u>Close-up:</u> Illegally welded fitting on 12" ImoRiver2 pipeline at Odagwa. Picture taken during Joint Investigation of 17<sup>th</sup> June, 2011

1



<u>Close-up:</u> Illegally welded fittings on 12" ImoRiver2 pipeline at Odagwa. Picture taken during Joint Investigation of 18th June, 2011



<u>Close-up:</u> Illegally welded fitting on 12" ImoRiver2 pipeline at Odagwa. Picture taken during Joint Investigation of 18th June, 2011



<u>Close-up:</u> Illegally welded fitting on 12" ImoRiver2 pipeline at Odagwa. Picture taken during Joint Investigation of 18th June, 2011