

Overview: Part of spill impact on 16" Eriemu-UPS trunkline right of way at Iwhremaro. Picture was taken during Joint Investigation of 27th August 2012.



Close up: Hacksaw cut on 16" Eriemu-UPS trunkline at Iwhremaro. Picture was taken during Joint Investigation of 27th August 2012.

1