

<u>Close-up:</u> Spill due to failed clamp on Cawthorne Channel Well 45T flowline at Mbiama. Picture taken during Joint Investigation of 13th August, 2011.

1