

Overview: Part of spill impact on 20" Ughelli Pumping Station to Warri Refinery Petrochemical Company trunkline right of way at Ugbomro. Picture taken during Joint Investigation of 13th October, 2011.



<u>Close-up:</u> Spill due to failed clamp on 20" Ughelli Pumping Station to Warri Refinery Petrochemical Company trunkline at Ugbomro. Picture taken during Joint Investigation of 13th October, 2011.

1