

Overview: Spill point on Ejeamah-Ebubu Well5/9 flowline at Ejeamah. Picture was taken during Joint Investigation of 19th June 2012.

1