

Overview: Extent of the spill incident impact on Umuechem well 22T Flowline route at Umuechem. Picture taken during Joint Investigation of 25th March, 2011



<u>Close-up:</u> Spill due to corrosion on Umuechem well 22T Flowline at Umuechem. Picture taken during Joint Investigation of 25<sup>th</sup> March, 2011.

1