

Overview: Extent of the spill incident impact on Kolocreek Well 3T flow line at Otosiga. Pictures taken during Joint Investigation of 1st March, 2011.



<u>Close-up:</u> Spill due to hacksaw cut on Kolocreek Well 3T flow line at Otosiga. Picture taken during Joint Investigation of 1st March, 2011.