

Overview: Extent of the spill incident impact on  $8^{\prime\prime}$  Obigbo-North Pipeline at Obigbo . Pictures taken during Joint Investigation of  $25^{\rm th}$  March, 2011



<u>Close-up:</u> Spill was due to illegally welded point on  $8^{\prime\prime}$  Obigbo-North Pipeline at Obigbo. Picture taken during Joint Investigation of  $25^{\text{th}}$  March, 2011.