

Overview: Part of spill impact on Yokri Manifold7 Low Pressure1 line right of way at Sokebolou. Picture was taken during Joint Investigation of 10th May 2013.



<u>Close up</u>: Leak due to corrosion on Yokri Manifold7 Low Pressure1 line at Sokebolou. Picture was taken during Joint Investigation of 10th May 2013.

1