

<u>Close-up:</u> Spill due to corrosion on 12" Adibawa-Okordia pipeline at Ikarama. Picture was taken during Joint Investigation of 16th November, 2011.