

Overview: Part of the spill impact on 2" Imoriver pipeline at Uzuaku. Picture taken during Joint Investigation of 29th June, 2011



<u>Close-up:</u> Spill due to illegal fittings on 12" Imoriver pipeline at Uzuaku. Picture taken during Joint Investigation of 29th June, 2011

1