

<u>Close up</u>: Spill due to corrosion on 4" Cawthorne Channel 2 Well 29T flowline at Mbiama. Picture was taken during Joint Investigation of 4th September 2013.

1