

<u>Close-up:</u> Spill due to structural failure on Krakama Well13 at Bille. Picture was taken during Joint Investigation of 28th November, 2011.

1