

Overview: Part of spill impact on 6" Utorogu-Ughelli West gasline at lwhrekan. Picture taken during Joint Investigation of 25th August, 2011.



<u>Close-up:</u> Spill due to damage by 3rd party equipment on 6" Utorogu-Ughelli West gasline at Iwhrekan. Picture taken during Joint Investigation of 25th August, 2011.

1