

<u>Close up</u>: Illegal fittings on 6" Imo River 59T flowline at Igiriukwu. Picture was taken during Joint Investigation of 18th September 2013.

1