

Overview: Part of spill impact on 16" Eriemu-UPS trunkline right of way at Ekiugbo. Picture was taken during Joint Investigation of 16th October 2012.



<u>Close up:</u> Illegal fittings on 16" Eriemu-UPS trunkline at Ekiugbo. Picture was taken during Joint Investigation of 16th October 2012.

1