

Overview: Part of spill incident impact at 20" Kolocreek–Rumuekpe Pipeline right of way at Ogbogolo. Picture was taken during JIV of 23^{rd} September, 2011



<u>Close-up:</u> Spill due to failed clamp on 20" Kolocreek–Rumuekpe Pipeline at Ogbogolo.
Picture was taken during JIV of 23rd September, 2011

1