

Overview: Part of spill impact on 8" Obigbo North New Elelenwo pipeline at Akpajo.
Picture taken during Joint Investigation of 19th August, 2011.



<u>Close-up:</u> Spill due to corrosion on 8" Obigbo North New Elelenwo pipeline at Akpajo. Picture taken during Joint Investigation of 19th August, 2011.

1