

<u>Close up</u>: Spill due to corrosion on 10" Ekulam2 – Sanbarth pipeline at Sanbarth.. Picture was taken during Joint Investigation of 28th December 2012.

1