

Overview: Part of spill impact on 6" Obigbo North – Ebubu pipeline right of way at Obolo. Picture was taken during Joint Investigation of 13th October 2013.



<u>Close up</u>: Spill due to corrosion on 6" Obigbo North – Ebubu pipeline at Obolo. Picture was taken during Joint Investigation of 13th October 2013.

1