

Overview: Part of spill impact on 20" WRPC trunkline right of way at Ekpan. Picture taken during Joint Investigation of 22nd July, 2011



<u>Close-up:</u> Spill due to illegal fittings on 20" WRPC trunkline at Ekpan. Picture taken during Joint Investigation of 22nd July, 2011

1