

Overview: Part of spill impact on on 4" Obele delivery line right of way at Ibaa. Picture taken during Joint Investigation of 21st July, 2011



Close-up: Spill due to drilled hole on 4" Obele delivery line at Ibaa. Picture taken during Joint Investigation of 21st July, 2011

1