

Overview: Part of spill impact on 10" Otorogu-UPS delivery line at Otujeremi. Picture taken during Joint Investigation of 23rd July, 2011



<u>Close-up:</u> Spill due to illegal fitting on 10" Otorogu-UPS delivery line at Otujeremi. Picture taken during Joint Investigation of 23rd July, 2011

1