

Overview: Part of spill impact on 10" Ekulama 1 pipeline at Freetown. Picture taken during Joint Investigation of 28th July, 2011.



Close-up: Spill due to corrosion on 10" Ekulama 1 pipeline at Freetown. Picture taken during Joint Investigation of 28th July, 2011.

1