

Overview: Part of spill impact affecting farmland around Chokota gathering manifold at Obigbo. Picture taken during Joint Investigation of 19th July, 2011



<u>Close-up:</u> Spill due to illegal removal of Kerotex valve from Chokota gathering manifold at Obigbo. Picture taken during Joint Investigation of 19th July, 2011

1



<u>Close-up:</u> Replacement Kerotex valve on spill point at Chokota gathering manifold at Obigbo. Picture taken during Joint Investigation of 19th July, 2011