

Overview: Part of spill impact on Kanbo Well7S flowline right of way at Egbemoangarabiri/Agbidiama.



<u>Close up</u>: External corrosion on Kanbo Well7S flowline at Egbemoangarabiri/Agbidiama. Picture was taken during Joint Investigation of 26th September 2013.

1