

Overview: Part of spill impact on Otumara Well20L flowline right of way at Ugboegungun. Picture was taken during Joint Investigation of 24th October 2012.



<u>Close up:</u> Spill due to pinhole on Otumara Well20L flowline at Ugboegungun. Picture was taken during Joint Investigation of 24th October 2012.

1