

SOM Review


Copy of Property	
Created	@Jan 7, 2021 3:51 PM
DOC	review comments .docx
Property 1	
Tags	




why there are two grounds vias.png




why tracks are so tiny for the VDDMP.png




why this track is so tiny.png




check this too.png



Why this track is done like that.png



check this track.png



Check this connection.png



check.png

Resistor array are so big

MOSfet protection has very high power rating

Shotcky diode is 40V

Inductor is so big as will

regulator is so big