



$$Q_{CF} = \frac{Q_C}{3} = -\omega C_Y U_F^2 = \frac{-\omega C_Y U_L^2}{3}$$

$$C_Y = \frac{-Q_C}{U_L^2 \cdot \omega}$$