



$$Q_{CF} = \frac{Q_C}{3} = -\omega C_\Delta U_F^2 = -\omega C_\Delta U_L^2$$

$$C_\Delta = \frac{-Q_C}{3 \cdot U_L^2 \cdot \omega}$$