

UltAI Viewer User Guide - Version: 0.1.0

Notes and Disclaimers

- This is a beta release; features and results may change.
- Results are for research use only and require clinical validation.
- This guide is mostly AI-generated and may have errors.

Supported OS

- Windows: download
- Linux: [UltrAIViewer-v0.1.0-linux-x86_64.tar.gz](#)

macOS is not supported currently.

Compute Requirements

- CPU-only.
- Recommended: modern 4+ core CPU and 8+ GB RAM.

Supported Images and ROI

- Image type: 2D knee ultrasound images.
- Preferred format: grayscale TIFF, PNG, JPEG are also supported.
- Recommendation: use clean, well-cropped ROI images for best segmentation.

Quick Start

1. Launch the app (UltAIViewer.exe on Windows, UltAIViewer on Linux).
2. Load an image: File > Load Image.
3. Select a model (left panel, Model dropdown).
4. Click Segment to run inference.
5. Edit results if needed (Freehand Line, Segmented Line, Paint Brush, Eraser).
6. Save the mask: File > Save Mask (PNG recommended).

Segmentation (Single Image)

1. Load an image.
2. Choose the model.
3. Click Segment.
4. Wait for the progress dialog to finish.

5. Edit the mask if needed.

Batch Segmentation (Image sequence)

1. Click "Load image sequence".
2. Select a folder or select multiple images.
3. Choose an output folder.
4. Click Batch segment.
5. Wait for the progress dialog to finish.

Results are saved automatically in the output folder as PNG files. You can preview results by navigating through the loaded images using the left/right arrow keys.

Editing Tools

- Freehand Line: draw an outline ROI.
- Segmented Line: click to add points, right-click or double-click to finish.
- Paint Brush: add mask.
- Eraser: remove mask.
- Tool Radius: controls edit thickness.
- Fill ROI: unchecked shows contour; checked fills the ROI into the mask.
- Ctrl+Z to undo, Ctrl+Y to redo.

Zoom and Scroll

- Ctrl + scroll: zoom in/out.
- Shift + scroll: horizontal scroll (when zoomed).
- Scroll: vertical scroll (when zoomed).

Saving

- Save Mask: saves the current mask as PNG.
- If a batch output folder is selected, Ctrl+S saves directly to that folder.

Tips

- If the image looks too dark or bright, check the original export.

Troubleshooting

- "Unsupported image layout": the file is not a standard 2D or RGB image.
- If batch results are empty, check image quality and orientation.