

FLEECA

Command Center

Vehicles

Alerts

Map

Analytics

Reports

Maintenance

Users & Roles

Settings

Arun Kumar

Fleet Manager

Search vehicle, fleet, region...Ctrl /

All Regions

04 Jun 2026, 04:35 PM

34

Fleet Command Center

Real-time overview of your fleet health and alerts

7Critical700 PSIView all

53Warning305 PSIView all

842Stable700 PSIView all

14Disconnected205 PSIView all

21High PSI235 PSIView all

35Low PSI706 PSIView all

Fleet Health by Region

South Region

7100100%

West Region

5100100%

North Region

4100100%

East Region

3100100%

Active Alerts (84)

View all alerts

TN45AB12342LOLow PSI112 PSI4m ago

GJ09CD89121ROHigh PSI156 PSI6m ago

MH12EF34562RILow PSI110 PSI8m ago

RJ14AB3322AllNo Data12m ago

KAS1GH67891LOLow Battery18%15m ago

Fleet Map

1-5 of 84

Quick Filters

StatusCritical, Warning, +2

PSIHigh PSI, Low PSI

BatteryLow Battery

TemperatureHigh Temp

Vehicle TypeAll Types

RegionAll Regions

Clear All

Save View

Fleet Overview (1,256 Vehicles)

Vehicle No.	Vehicle Type	Region	Health Score	Status	PSI (Avg)						Temp (°C)		Last Update	Actions
					1LO	1RO	2LO	2RO	2LI	2RI	Max	Battery		
TN45AB1234	Forklift	Chennai		Critical	136	138	112	139	134	137	46	82%	4m ago	
GJ09CD8912	Hyster 46-33CH	Gujarat		Warning	145	147	140	155	142	143	42	76%	6m ago	
KAS1GH6789	Forklift	Bangalore		Warning	138	139	135	136	137	134	40	18%	8m ago	
MH12EF3456	Hyster 46-33CH	Maharashtra		Critical	135	136	110	141	133	138	47	70%	8m ago	
RJ14AB3322	Reach Truck	Rajasthan		Disconnected	-	-	-	-	-	-	-	-	12m ago	

Vehicle 360° View

TN45AB1234Critical

Forklift • Chennai, Tamil Nadu

Health Score

42/100

Critical

Live Tire Status

1LO136 PSI32 °C82%

1RO136 PSI33 °C80%

2LO112 PSI34 °C82%

2RO139 PSI33 °C80%

2LI134 PSI31 °C82%

2RI137 PSI30 °C81%

Active Issues (2)

Low PSI

2LO – 112 PSI

Recommended: 145 PSI

Low Battery

Sensor: 2LO

Battery: 18%

PSI Trend (2LO)

Last 6 Hours

Activity Timeline

View Full History

04 Jun 2026

04:31 PM

Low PSI detected in 2LO

112 PSI

04:29 PM

PSI dropped below threshold

120 PSI

04:25 PM

Low Battery in 2LO sensor

18%

Alert Operations Center

Manage and resolve fleet alerts in real-time

All (84)

Critical (21)

Warning (39)

Info (24)

Resolved

Auto Refresh

Sort by: Latest

Filters

Time	Vehicle No.	Type	Position	Issue	Value	Recommendation	Actions
04:31 PM	TN45AB1234	2LO	Low PSI	Critical	112 PSI	Inflate to 145 PSI	
04:29 PM	GJ09CD8912	1RO	High PSI	Critical	156 PSI	Reduce to 145 PSI	
04:28 PM	MH12EF3456	2RI	Low PSI	Critical	110 PSI	Inflate to 145 PSI	
04:27 PM	KAS1GH6789	All	Low Battery	Critical	18%	Replace Sensor	
04:26 PM	RJ14AB3322	All	No Data	Critical	-	Check Connection	

Assign

Acknowledge

Resolve

Add Note

1-5 of 21

Analytics & Insights

AI-powered insights to optimize your fleet performance

14Vehicles at risk

May become critical in 24h

23Low battery sensors

Need attention

₹ 2.45L

Potential savings

By maintaining proper PSI

98.2%

Fleet uptime

Last 30 days

PSI Distribution

High PSI (>150)21 (0.7%)

Normal (130-150)1,034 (82.3%)

Low PSI (<130)201 (16.0%)

Top Issues

Low PSI

421

High PSI

123

Low Battery

89

High Temperature

32

No Data

14

Issue Trend (Last 7 Days)

Notifications

Real-time alerts and updates

All (64)

Critical (21)

Warning (39)

Info (24)

Search notifications...

All Types

All Regions

Date: Today

04:31 PMCriticalCritical

TN45AB1234

112 PSI detected. Recommended: 145 PSI

Chennai, Tamil Nadu

AcknowledgeAssign

04:29 PMWarningWarning

GJ09CD8912

156 PSI detected. Recommended: 145 PSI

Gujarat

AcknowledgeAssign

04:28 PMWarningWarning

KAS1GH6789

Sensor battery at 18%. Replace soon.

Bangalore, Karnataka

AcknowledgeAssign

