
P|A
A|Q
B|M
Q'
PARALLEL ADDER
OUTBUS
INBUS
MULTIPLIER COUNT
COUNT3
COUNT7
begin
reset
clock
end
CONTROL UNIT