

SYNTHETIC TEST DOCUMENT — LIFE SCIENCES QUALITY ASSURANCE TEST DATASET — STRICTLY FOR DEMONSTRATION & VALIDATION

Peristaltic Pump Mechanical Breakdown during Sterile Vial Filling

1. GENERAL INCIDENT INFORMATION

Date of Occurrence:	2026-09-19	Discovery Source:	Filling Line Operator Visual & Acoustic Inspection
Manufacturing Site:	Formulation & Filling Suite C, Raleigh Plant	Department / Area:	Aseptic Fill-Finish Operations
Related Product / Material:	Sterile Saline Diluent (50 mL Vials)	Batch / Lot Number:	LOT-99201

2. EVENT SUMMARY & DEVIATION DESCRIPTION

Peristaltic dosing pump P-102 suffered mechanical bearing seizure at vial fill count 4,120 of 10,000 scheduled units, causing uneven fill volumes and hose pinching in Grade A filling cabinet.

3. IMMEDIATE ACTIONS & CONTAINMENT MEASURES

The sterile filling line was stopped immediately. The operator quarantined 150 vials filled immediately prior to pump failure and discarded the damaged silicone tubing set.

4. INITIAL LOGGING VERIFICATION

Logged By: Operations Shift Lead Date: 2026-09-19	QA Reviewer: Quality Assurance On-Duty Date: 2026-09-19	Workflow Stage: Awaiting AI Extraction & Human Review
--	--	---