

PHARMACEUTICAL QUALITY MANAGEMENT SYSTEM
DEVIATION INCIDENT REPORT

Deviation ID: DEV-2026-SITE-101

Date of Occurrence: 2026-04-12

Site: Dublin Sterile Manufacturing Facility (Site IRL-04)

Department: Aseptic Fill-Finish Operations

Source / Detection: Line Inspector Visual In-Process Control

Incident Title: High-Speed Vial Capping Torque Parameter Under-Torque Excursion

Related Product: Monoclonal Antibody Solution for Infusion 100mg

Batch Number: MAB-8842

Event Description:

During primary packaging and seal crimping of Batch MAB-8842 at Dublin Site IRL-04, optical torque sensor on Capper Head

Immediate Containment Action:

Capping line stopped immediately. All 420 potentially affected vials were segregated and quarantined under physical QA